


**CORNER RECORD**

Document Number 559

City of \_\_\_\_\_

County of Sacramento, California

Brief Legal Description: Marysville Blvd. North of Elkhorn Blvd. 34 RS 18



**CORNER TYPE**

**COORDINATES**

(Optional)

Government Corner ( )	Control ( )	N. _____
Meander ( )	Property (X)	E. _____
Rancho ( )	Other ( )	Zone _____ Datum _____
Date of Survey <u>April 2, 1999</u>		Elev. _____

Corner- Left as found ( ) Found and tagged ( ) Established ( ) Reestablished (X) Rebuilt ( )

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

On April 14, 1998, found concrete nail and Button head spike and washer on Marysville Blvd. North of Elkhorn Blvd.  
As per 34 RS 18. Monuments were referenced before A/C overlay. See County of Sacramento Field Notes Vol.  
A-221.

A description of the physical condition of the monument as found and as set or reset:

On April 2, 1999, replaced concrete nail with 3/4" Iron Pipe and Sac. Co. P.W. tag in monument well and set a monument well  
Over existing button head and washer both from references.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with The Land Surveyors' Act on April 19 19 99.

Signed William M Carmack L.S. or P.C.E. Number 5887



**COUNTY SURVEYOR'S STATEMENT**

This corner Record was received June 28, 19 99 and examined and filed June 30 19 99

Signed [Signature] Title Supervisor - Map Checking

County Surveyor's Comment \_\_\_\_\_

NOT TO SCALE



NOTE: FND. CONCRETE  
NAIL PER 34 RS 18 AND  
RESET WITH 3/4" I.P.  
AND SAC. CD. P.W. TAG  
IN MONUMENT WELL

206.98  
~~(206.83)~~

835.00  
~~(835.00)~~

MARYSVILLE BLVD.

**34 RS 18**

ELKHORN BLVD.

LEGEND:

● SET MONUMENT WELL OVER  
EXISTING BUTTON HEAD AND  
WASHER SET DN 5/8" X 36"  
REBAR PER 34 RS 18

● SET 3/4" IRON PIPE WITH  
SAC. CD. P.W. TAG IN MON-  
UMENT WELL

( ) RECORD DISTANCE AS PER  
34 RS 18