


CORNER RECORD

Document Number 2399

City of _____

County of SACRAMENTO, California

Brief Legal Description ☒ MONUMENTS, PARKWAY ESTATES UNIT NO. 1



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey NOVEMBER 16, 2010

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 1" IRON PIPES WITH NO TAG AS SHOWN ON PAGE 2 OF 2. MEASUREMENT BETWEEN THE FOUND MONUMENTS WAS NOT PERFORMED. ONLY RECOVERY OF THE MONUMENT WAS PERFORMED. THE MONUMENTS WERE RECOVERED IN ANTICIPATION FOR USE IN A BOUNDARY SURVEY WHICH DID NOT MATERIALIZE.

A description of the physical condition of the monument as found and as set or reset:
THE FOUND MONUMENTS WERE FOUND FIRMLY SET.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DECEMBER 8, 2010

Signed Michael Kindler P.L.S. or R.C.E. Number 6176



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12/9, 2010 and examined and filed 12/10, 2010

Signed [Signature] P.L.S. or R.C.E. Number 7965

Title ASSOC. L.S.

County Surveyor's Comment _____



LEGEND:

- FOUND 1" IRON PIPE, NO TAG
- DIMENSION POINT, NOTHING FOUND

