


CORNER RECORD

Document Number 689

City of Sacramento

County of Sacramento, California

Brief Legal Description: Lot 8, Block 5 of 12 BM 22, "Por. North Sacramento Heights"



CORNER TYPE

COORDINATES
(Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey: 12/15/01

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

The rights-of-way of Ford Road and Rio Linda Boulevard were established by a split of improvements. The property lines were established by using record distances to offset the right-of-way lines.

A description of the physical condition of the monument as found and as set or reset:

5/8" rebars with plastic caps titled "L.S. 5532" were set at the northwest and southwest property corners.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 19th, 2001.

Signed Craig Wecker L.S. Number 5532
Craig Wecker



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 21, 2001 and examined and filed December 24, 2001.

Signed Paul Parker Title Supervisor - Map Checking

County Surveyor's Comment: _____

LOT 6
12 BM 22

LOT 7
12 BM 22

ALLEY

N89°57'19"E 45.00'

BLOCK 5



Scale: 1" = 20'

LOT 9
12 BM 22

LOT 8
12 BM 22

Rio Linda Boulevard

(Split of Improvements)

North

North

South

120.00'

120.00'

40.00'

S89°57'19"W 45.00'

Ford Road

N89°57'19"E
(Split of Improvements)

LEGEND

- ⊗SET 5/8" REBAR W/ PLASTIC CAP "L.S. 5532"
-DIMENSION POINT (NOTHING FOUND, NOTHING SET)