

CORNER RECORD

Document Number 1169

City of N/A

County of SACRAMENTO, California

Brief Legal Description PARCEL "C" as shown on the Parcel Map filed in 29 PM 27

CORNER TYPE

COORDINATES
(Optional)

Government Corner Control N. _____
 Meander Property E. _____
 Rancho Other Zone _____ Datum _____
 Date of Survey _____ Elev. _____

Corner Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found monuments per 29 PM 27 (see page 2). Reset the most N'ly corner of Parcel "C" by:
1) occupying the most E'ly corner of Parcel "C", 2) backsighting the most S'ly corner of
Parcel "C", 3) checking the location of the most W'ly corner of Parcel "C" and the most
N'ly corner of Parcel A (29 PM 27), and 4) turning the record angle and distance to said
corner.

A description of the physical condition of the monument as found and as set or reset: _____
Condition of all monuments (found or set) is good. See page 2 for monument descriptions.



SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on JANUARY 28 20 05.

Signed David L. Humphreys L.S. or R.C.E. Number L.S. 5920 (exp. 12/31/06)

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 4, 19 2005 and examined
 and filed FEBRUARY 15, 19 2005.

Signed William M. Carmack Title SR. LAND SURVEYOR

County Surveyor's Comment: _____



FOUND 3/4" REBAR (NO TAG)
PER 29 PM 27 & 128 PM 25

BRADLEY RANCH ROAD

PARCEL A
29 PM 27

SET 3/4" REBAR WITH PLASTIC
CAP STAMPED LS 5920

PARCEL B
29 PM 27

FOUND 3/4" REBAR TAGGED LS 3646
PER 29 PM 27

PARCEL C
29 PM 27

FOUND 3/4" REBAR TAGGED LS 3646
PER 29 PM 27



ROSE'S ENGINEERING

ENGINEERING SURVEYING PLANNING
9152 ELK GROVE BLVD. ELK GROVE, CA 95624
BUS.(916) 686-5445 FAX(916) 685-8900

PARCEL "C" OF 29 PM 27
CORNER RECORD

DATE: 01/28/2005

SCALE: 1" = 100'

JOB NO.
1905-04
SHEET No.

2 OF 2