

CORNER RECORD

COUNTY OF SACRAMENTO 7N 5E MDM NEEDHAM CALIFORNIA

CORNER TYPE: BUILT CORNER BEARINGS BENCHING CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT _____



Section 2

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OR REPERCEIVED CORNER REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENT RESULT OR REPERCEIVED

CALIFORNIA COORDINATE SYSTEM DESIGN: FIRST SECOND THIRD OTHER
 STATIONS USED: NAD 83 (NAD 83) STATE COUNTY OTHER STATION _____ STATION _____
 BENCH _____ BEYOND _____ NORTHINGS (N) _____ EASTINGS (E) _____

[Faint handwritten text]

SKETCH (Indicate references to or within points, records and tops of areas)



SECTION'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME, OR UNDER MY
 SUPERVISION IN CONFORMANCE WITH THE SURVEYING ACT
 OF CALIFORNIA.
 DATE: 09-10-87
 BY: [Signature]
 TITLE: Surveyor
 EXPIRATION DATE: 09-10-88

CORNER IDENTIFIER'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED MAY 1987
 AND EXAMINED AND FOUND TRUE 1987
 BY: [Signature]
 TITLE: Supervising Eng. Tech
 DOCUMENT NO. 123
 DATE OF VISIT: _____