


# CORNER RECORD

City of ELK GROVE

Document Number 1809

County of SACRAMENTO, California

Brief Legal Description \_\_\_\_\_



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

### CORNER TYPE (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.  
FOUND 3/4" IRON PIPE IN CENTERLINE OF PARK MEADOWS DRIVE PER 114RM5.

A description of the physical condition of the monument as found and as set or reset. \_\_\_\_\_

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 18, 2007.


Signed Scott A. Bryan L.S. or R.C.E. Number 7228

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11/22 2007.  
and filed 11/27 2007.

Signed Larry S. Savio Title ASSOC. L.S.

County Surveyor's Comment \_\_\_\_\_



### LEGEND

- x SET LEAD & TAG STAMPED LS 7228
- o FOUND 3/4" IRON PIPE PER 114RM5
- ADDRESS

