


CORNER RECORD

City of ELK GROVE

Document Number 1829

County of SACRAMENTO, California

Brief Legal Description _____



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

CORNER TYPE (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.
FOUND 3/4" IRON PIPE IN CENTERLINE OF EMERALD OAKS DRIVE PER 97RM6.

A description of the physical condition of the monument as found and as set or reset. _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 19, 2007.

Signed Scott A. Bryan (L.S.) or R.C.E. Number 7228



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11/22 2007.

and filed 11/27 2007.

Signed Larry S. Savio Title ASSOC. L.S.



County Surveyor's Comment _____

LEGEND

- x SET LEAD & TAG STAMPED LS 7228
- o FOUND 3/4" IRON PIPE PER 97RM6
- ADDRESS



NOT TO SCALE

