


CORNER RECORD

Document Number 2099

City of ELK GROVE

County of SACRAMENTO, California

Brief Legal Description _____



CORNER TYPE

CORNER TYPE (Optional)

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.
FOUND 3/4" IRON PIPE IN CENTERLINE OF EMERALD VISTA DRIVE PER 115 RM 16, S.C.R.

A description of the physical condition of the monument as found and as set or reset. _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on March 5, _____ 2009.

Signed Scott A. Bryant L.S. or R.C.E. Number 7228



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3/19 2009.

and filed 3/24 2009.

Signed [Signature] Title ASSOC. L.S.



County Surveyor's Comment _____

LEGEND

Document Number _____

- x SET LEAD & TAG STAMPED LS 7228, AT BACK OF WALK
- o FOUND 3/4" IRON PIPE PER 115 RM 16, S.C.R.
- STREET ADDRESS



NOT TO SCALE

