


CORNER RECORD

Document Number 2249

City of _____

County of Sacramento, California

Brief Legal Description Lot 116, Rancho Grande Unit No. 3, Book 61, Map No. 27



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey April 2, 2010

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- Found 3/4" Iron Pipe, as noted
- └ Found sawcut at back of sidewalk, as noted

A description of the physical condition of the monument as found and as set or reset:

- Found 3/4" Iron Pipe below surface of asphalt paving, accepted as centerline Mary Ellen Way per 61/BM/27
- ♂ Set 3/4" rebar with brass tag L.S. 5123 SE Corner Lot 116, 61/BM/27

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on APRIL 5, 2010

Signed Stu A. Gehr (P.L.S.) or R.C.E. No. 5123



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4/15/2010

and examined and filed 4/15/2010

Signed [Signature] (P.L.S.) or R.C.E. No. 7965

Title ASSOCIATE LAND SURVEYOR



County Surveyor's Comment _____

