


# CORNER RECORD

Document Number 2419

City of ELK GROVE

County of SACRAMENTO, California

Brief Legal Description \_\_\_\_\_



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey October 7, 2010

### CORNER TYPE (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.  
FOUND 3/4" IRON PIPE IN CENTERLINE OF RIVER OTTER WAY PER 239 RM 3, S.C.R.

A description of the physical condition of the monument as found and as set or reset. \_\_\_\_\_

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on November 1, 2010.

Signed Scott A. Bryant L.S. or R.C.E. Number 7228

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12/28 2010  
and filed 1/4 2011.

Signed Larry S. Savio Title ASSOC. L.S.

County Surveyor's Comment \_\_\_\_\_



# LEGEND

Document Number \_\_\_\_\_

x SET LEAD & TAG STAMPED PLS 7228 AT BACK OF WALK

o FOUND 3/4" IRON PIPE, PER 239 RM 3, S.C.R.

7727 STREET ADDRESS

