


CORNER RECORD

Document Number 2449

City of ELK GROVE

County of SACRAMENTO, California

Brief Legal Description _____



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey July 9, 2010

CORNER TYPE (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.
FOUND 3/4" IRON PIPE IN CENTERLINE OF TRALEE WAY PER 105 RM 5, S.C.R.

A description of the physical condition of the monument as found and as set or reset. _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 14, 2010.

Signed Scott A. Bryan LS or R.C.E. Number 7228.



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 12/28 2010.

and filed 1/4 2011.

Signed [Signature] Title ASSOC. C.S.

County Surveyor's Comment _____

LEGEND

Document Number _____

- x SET LEAD & TAG STAMPED PLS 7228 AT BACK OF WALK
- △ SET LEAD & TAG STAMPED PLS 7228 IN TOP OF CURB
- FOUND 3/4" IRON PIPE, PER 105 RM 5, S.C.R.

9796 STREET ADDRESS



NOT TO SCALE

