


CORNER RECORD

Document Number 899

City of _____

County of Sacramento, California

Brief Legal Description: Beginning of a 1200.00' Radius Curve in Don Julio Bl., Hillsdale Unit No 28



CORNER TYPE

COORDINATES

(Optional)

Government Corner () Control () N. _____
 Meander () Property (X) E. _____
 Rancho () Other () Zone _____ Datum _____
 Date of Survey September 13, 2001 Elev. _____

Corner- Left as found () Found and tagged () Established () Reestablished (X) Rebuilt ()

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

On September 13, 2001 found 3/4" iron pipe at the beginning of a 1200.00' radius curve, 28.07' west from the intersection of Don Julio Bl. and Sprig Dr. as per 109BM11. Pipe was referenced before construction. See County of Sacramento Field Notes Vol. D-81.

A description of the physical condition of the monument as found and as set or reset:

In August, 2002 set 2" Brass Disc in monument well from references, stamped "Sacramento Co. Dept. of Public Works."

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

The Land Surveyors' Act on October 21 2002

Signed William M Carmack L.S. or R.C.E. Number 5887



COUNTY SURVEYOR'S STATEMENT

This corner Record was received Oct 30, 2002 and examined and filed Nov 4, 2002

Signed [Signature] Title Associate Land Surveyor

County Surveyor's Comment _____

